

The 2 earthquakes of February 6th 2023 in Turkey



Source: CNBC

Preliminary Report

by Evangelia GARINI and George GAZETAS




NTUA, Greece

PART A

Seismological Data of the M 7.8 and M 7.5 earthquakes

Tectonic setting-Intensity maps

7 February 2023



- Magnitude **Mw 7.8**
- Region **CENTRAL TURKEY**
- Date time **2023-02-06 01:17:36.1 UTC**
- Location **37.17 N ; 37.08 E**
- Depth **20 km**

- Magnitude **Mw 7.5**
- Region **CENTRAL TURKEY**
- Date time **2023-02-06 10:24:49.6 UTC**
- Location **38.11 N ; 37.24 E**
- Depth **10 km**

Map of seismic epicenters



Source: <https://www.emsc-csem.org/Earthquake/Map/gmap.php>

Map of seismic epicenters




Source: <https://www.emsc-csem.org/Earthquake/Map/gmap.php>

The **M 7.8** earthquake resulted from **strike-slip faulting** at shallow depth.

The event ruptured either a **near-vertical left-lateral fault** striking **northeast-southwest**, or a **right-lateral fault striking** **southeast-northwest**. The preliminary location of the earthquake places it within the vicinity of a triple-junction between the Anatolia, Africa and Arabian tectonic plates. **A magnitude 7.8 strike slip earthquake is associated with a rectangular fault rupture of ~240 km long and ~20 km wide.**


Nine hours after the first earthquake of **M 7.8**
a second earthquake of **M 7.5** occurred
100 km to the north






SEISMOLOGICAL INFO


Map showing main tectonic structures around the Anatolian Plate.
The arrows show displacement vectors of the Anatolian and Arabian Plates
relative to the Eurasian Plate




Tectonics and fault system Map of the East Anatolian Fault





Source: Duman and Emre (2013)



Source: CSEM-EMSC + GEM + USGS + Jason R. Patton
11







The 1st mainshock of M7.8

100 km
 — Political boundaries
 — Tectonic plates boundaries

Depth

- ★ 0 - 40 km
- ★ 40 - 80 km
- ★ 80 - 150 km
- ★ 150 - 300 km
- ★ > 300 km


EMSC manual location

M:7.8 2023/02/06 - 01:17:36 UTC


Lat: 37.17 Lon: 37.08 Depth: 20 km

Background data: ISC + EMSC catalogues from 1960 to 06/02/2023 01:00

(Total number of events with $M>3$: 18778)




Magnitude



100 km


Political boundaries
Tectonic plates boundaries (Bird, P. [2003])

Magnitude



Impact area of earthquakes in Türkiye


Earthquakes in Türkiye's southern region also felt in Syria, Egypt, Lebanon, Northern Cyprus and Iraq




Source: ANADOLU AGENCY 6

Hundreds dead in Turkey, Syria earthquake

Hundreds of people are dead and more than 1,700 buildings have collapsed after a magnitude 7.8 earthquake struck the southeastern region of Turkey along the border with Syria. Tremors were also felt across Lebanon and Cyprus.






Map of the seismic activity of February 6, 2023, near the Türkiye–Syria border. Fault lines are shown in black. The first magnitude 7.8 mainshock (yellow star) occurred at 01:17 AM (UTC) on the East Anatolian Fault system. The second magnitude 7.7 mainshock (01:24 PM UTC; yellow star) occurred about 100 km north of the first event on a distinctly separate fault.

The first mainshock broke along an ~350 km long stretch of the EAF, while the 2nd mainshock was ~170 km long.

Graphic courtesy of **P. Martin Mai and Sigurjon Jonsson, Earth Science and Engineering, KAUST.**

EU satellite precisely maps earthquake faults



Ground movement measured closer to or further away from passing satellite

Source: Copernicus data, Esa, Comet 2023

BBC

PRELIMINARY REPORT

Failures of Multistorey Buildings

in Turkey and Syria

Due to the M 7.8 and M 7.5 Earthquakes

PART B: Structural Collapse and Interpretation

PART C: Recorded Accelerograms, Response Spectra

Evangelia GARINI and George GAZETAS

8 February 2023



**School of Civil Engineering,
National Technical University of Athens**

PART B

Some Remarks on the STRUCTURAL * Collapse of Multistorey Buildings

*** and one purely GEOTECHNICAL Failure**

Based on the following photos, and our experience from the Kocaeli (1999) earthquake, we draw some conclusions regarding the unprecedented extent of damage. In addition to the very strong seismic shaking, with PGAs in the order of at least 0.7 g – 1 g, the following structural deficiencies (that are clearly identified in these photos and are evident in perhaps all the collapsed buildings) were truly fatal:

1. Very thin columns, but rather thick slabs
2. Very inadequate steel reinforcement (in size and number of longitudinal bars)
3. Transverse reinforcing bars of inadequate density and improperly tied
4. NO beams !! Slabs constructed directly on columns, without continuity of the longitudinal Rebars, and no proper joints
5. Nowhere to be seen Shear Walls, even in > 10 story buildings

(For comparison, a typical 2-story building in Cephalonia, Greece, is shown — from an area of similar seismicity as the region inflicted by the 7.8 earthquake.)

Source: <https://en.armradio.am/2023/02/08/turkey-and-syria-quake-toll-nears-8000/>



See next slide for details



Numerous buildings without any beam, with small size columns
(inappropriate even for 1-story buildings in a region of moderate seismicity).²⁴



Creator: Ghaith Alsayed
Credit: AP

See next slide for details



NO BEAMS
NO SHEAR WALLS



Photo: Mahmoud Hassano/Reuters




See next slide for details



The slab is effectively
SIMPLY-SUPPORTED, as
just resting on top of the
thin columns !

**VERY THIN
COLUMNS**
**NO Slab-Column
JOINT**


See next slide for details





**Joints fail, as if
there is no
continuity of the
longitudinal
reinforcement
(REBARS).**

**Essentially, NO
Slab–Column JOINT**



See next slide for details

Source: https://en.as.com/latest_news/turkey-and-syria-earthquakes-live-updates-death-toll-nears-100000-earthquake-map-video-of-magnitude-78-quake-n/



**VERY FEW REBARS,
OF VERY SMALL
DIAMETER**



Photo: ymphotos/Shutterstock

See next slide for details




Transverse reinforcement almost effectively non-existing... it was untied, leading the inadequate longitudinal rebars to buckle.



Photo: Suhaib Salem/Reuters

See next slide for details



**Transverse bars
were un-tied.**

**Longitudinal
REBARS are of
VERY SMALL
DIAMETER**


**NO BEAMS, POOR (or rather No)
JOINTS !**



Photo: Mohammed Al-Rifai/AFP/Getty Images



See next slide for details





See next slide for details

Same building seen from a different angle





NO BEAMS, POOR JOINTS !

VERY FEW
REBARS OF
VERY SMALL
DIAMETER



Source: <https://www.rescue.org/article/earthquakes-near-turkish-syrian-border-deepen-crisis>

See next slide for details



**VERY THIN COLUMNS
NO BEAMS
POOR JOINTS**



See next slide for details





Longitudinal REBARS have penetrated the supported slab !!




Aerial photo shows the destruction in Kahramanmaraş, southern Turkey, Wednesday, Feb. 8, 2023. (Photo | AP)

See next slide for details



NO BEAMS, NO JOINTS, NO SHEAR WALLS





See next slide for details



Notice the deformed shape of this column !!

Inadequate columns cannot “follow” the above building on its lateral movement



See next slide for details



**FEW LONGITUDINAL REBARS,
OF VERY SMALL DIAMETER**

Transverse reinforcement ??

